

Message Text

UNCLASSIFIED

PAGE 01 STATE 036562
ORIGIN HEW-06

INFO OCT-01 EUR-12 ISO-00 OES-06 EB-08 COME-00 /033 R

DRAFTED BY DHEW/FDA: JRWEINROTH, M.D.:CCK
APPROVED BY OES/APT/BMP: WJWALSH, III
DHEW/PHS/OASH/OIH: RFISCHER
EUR/SE:EDSMITH(INFO)

-----171944 082539 /42

P 171910Z FEB 77
FM SECSTATE WASHDC
TO AMEMBASSY ANKARA PRIORITY

UNCLAS STATE 036562

E.O. 11652: N/A

TAGS: OGEN, ETRD, TBIO, TU

SUBJECT: DEFECTIVE OXYGENATOR SUPPORT CLAMP ASSEMBLY
(RECALL T-029-7)

REF: ANKARA 1007

1. FDA ADVISES THAT FIRM'S RECORDS INDICATE HACETTEPE UNIVERSITY HOSPITAL DOES POSSESS A HARVEY MODEL H-200 WHICH IS JUST AN OXYGENATOR. SUPPORT CLAMPS REQUIRED FOR PROPER OPERATION OF MODEL H-200. RECORDS OF FIRM (WILLIAM HARVEY RESEARCH CORP) FURTHER INDICATE THAT UNIVERSITY HOSPITAL HAS RECEIVED MODEL H-300 SUPPORT CLAMPS.

2. FDA REQUESTS EMBASSY CHECK RESPONSIBLE/KNOWLEDGEABLE INDIVIDUAL(S) (PUMP TEAM) AT UNIVERSITY HOSPITAL TO DETERMINE WHETHER MODEL H-200 BEING USED WITH MODEL H-300 SUPPORT CLAMPS OR CLAMPS OF ANOTHER FIRM AND TWX FDA AS TO ACTUAL SITUATION (TYPE OF SUPPORT CLAMPS, MANUFACTURER AND DATE RECEIVED).

UNCLASSIFIED

UNCLASSIFIED

PAGE 02 STATE 036562

HARTMAN

UNCLASSIFIED

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01-Jan-1994 12:00:00 am
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: MEDICAL CARE, EQUIPMENT, RECALLS
Control Number: n/a
Copy: SINGLE
Sent Date: 17-Feb-1977 12:00:00 am
Decaption Date: 01-Jan-1960 12:00:00 am
Decaption Note:
Disposition Action: n/a
Disposition Approved on Date:
Disposition Case Number: n/a
Disposition Comment:
Disposition Date: 01-Jan-1960 12:00:00 am
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1977STATE036562
Document Source: CORE
Document Unique ID: 00
Drafter: JRWEINROTH, M.D.:CCK
Enclosure: n/a
Executive Order: N/A
Errors: N/A
Expiration:
Film Number: D770057-0582
Format: TEL
From: STATE
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1977/newtext/t19770230/aaaabazi.tel
Line Count: 56
Litigation Code IDs:
Litigation Codes:
Litigation History:
Locator: TEXT ON-LINE, ON MICROFILM
Message ID: 9a9317c5-c288-dd11-92da-001cc4696bcc
Office: ORIGIN HEW
Original Classification: UNCLASSIFIED
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: n/a
Previous Handling Restrictions: n/a
Reference: 77 ANKARA 1007
Retention: 0
Review Action: RELEASED, APPROVED
Review Content Flags:
Review Date: 26-Nov-2004 12:00:00 am
Review Event:
Review Exemptions: n/a
Review Media Identifier:
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
SAS ID: 3293171
Secure: OPEN
Status: NATIVE
Subject: DEFECTIVE OXYGENATOR SUPPORT CLAMP ASSEMBLY (RECALL T-029-7)
TAGS: OGEN, ETRD, TBIO, TU
To: ANKARA
Type: TE
vdkgvwkey: odb://SAS/SAS.dbo.SAS_Docs/9a9317c5-c288-dd11-92da-001cc4696bcc
Review Markings:
Margaret P. Grafeld
Declassified/Released
US Department of State
EO Systematic Review
22 May 2009
Markings: Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 22 May 2009